

Fig. 1




Fig. 2

Start recording Bale moistures Auto Record 0 Manual Record Cursor Up **(** \odot Cursor Down Print Bale Moistures **Enter Lot Numbers** Enter Bale Numbers 0 Enter Date 0 Alert Set Point Entry -38

Fig. 3